





Order No.	Insert	Dimensions					K°	Insert Icon	Parts			Wrench
		D	F	L	B	Parts			Parts	Parts		
S12M-CTUPR/L11	TPMN1103	12	9	150	16	0°	—	—	CP50-27S		LW025	
S16Q-CTUPR/L11	TPMN1103	16	11	180	20	3°	—	—	CP50-21	CS7-5015	LW025	
S20R-CTUPR/L11	TPMN1103	20	13	200	25	3°	—	—	CP50-21	CS7-5015	LW025	
S25R-CTUPR/L16	TPMN1603	25	17	200	32	3°	SMT-321	CS20045	CP50-22	CS7-6024	LW030	
S32S-CTUPR/L16	TPMN1603	32	22	250	40	3°	SMT-321	CS20045	CP50-22	CS7-6024	LW030	



Order No.	Insert	Dimensions					K°	Insert Icon	Parts			Wrench
		D	F	L	B	Parts			Parts	Parts		
S20R-MCKNR/L12	CNMG1204	20	13	200	25	17°	—	LCS-511	CP50-26	CS7-5018	LW025	—
S25R-MCKNR/L12	CNMG1204	25	17	200	32	14°	—	LCS-511	CP50-22	CS7-6024	LW025	LW030
S32S-MCKNR/L12	CNMG1204	32	22	250	40	14°	SMC-432	LCS-617	CP50-22	CS7-6024	—	LW030
S40T-MCKNR/L12	CNMG1204	40	27	300	50	12°	SMC-432	LCS-617	CP50-22	CS7-6030	—	LW030
S50U-MCKNR/L12	CNMG1204	50	35	350	63	12°	SMC-432	LCS-617	CP50-22	CS7-6030	—	LW030